

## GAS WELL INSPECTION REPORT

**Pad Site/Gas Well:** Furst Ranch C Pad (GW-04-04)

**X = compliance, \* = deficiency noted**

**Operator:** EAGLE RIDGE ENERGY, LLC

Inspection Date	Signage	Perimeter Condition	Screening & Landscaping	Surface Equipment	Notes	Remarks
4/22/2013	*	*	X	X	(JPOW) REMOVE OUT-DATED INFO FROM SIGNS  (JPOW) REMOVE WEEDS NEAR WELLHEADS AND NEAR SEPARATORS.	
6/13/2013	X	X	X	X		
7/24/2013	X	X	X	X		
8/21/2013	*	X	X	X	(BBAM) SIGNS ON THE SEPARATORS SAY "EAGLE ROCK" WITH THE WRONG EMERGENCY RESPONSE NUMBER. SIGNS NEEDS TO BE REPLACED.	
9/30/2013	X	X	X	X		
10/28/2013	X	X	X	X		
12/2/2013	X	X	X	X		
1/2/2014	X	X	X	X		
1/31/2014	X	X	X	*	(JLUX) air monitoring took place on Jan. 28th. leak was found at the wellhead bottom. Leak was fixed the next day.	
2/27/2014	X	X	X	X		
3/28/2014	X	X	X	X		
4/28/2014	X	X	X	X		
5/29/2014	X	X	X	X		
6/23/2014	X	X	X	X	(JLUX) air monitoring was at normal operating levels.	
7/16/2014	X	X	X	X		

8/7/2014	X	X	X	X	(JLUX) modern goesciences air monitoring inspection was conducted on July 28th. the reinspection was done on C pad 8-7-14. Eric Delaughter was onsite to witness inspection. The Mallard level control couplings were still admitting gas at the separators and crew was sent to fix the leaks. Wellheads had no leaks. tanks are not in use but NORM stickers will be placed on tanks. the tanks will be removed at a later date.	
9/9/2014	X	X	X	X		
11/24/2014	X	X	X	X	(JLUX) no leaks found during inspection.	
12/31/2014	X	X	X	X		
1/20/2015	X	X	X	X	(JLUX) conducted air monitoring inspection with Modern Geosciences. No leaks were detected during the inspection. The tanks had elevated norm levels above 50. Operator needs to label the tanks with the norm sticker.	
2/11/2015	X	X	X	X		
3/10/2015	X	X	X	X		
4/27/2015	X	X	X	X	(JLUX) tall weeds and grass on site	
5/11/2015	X	X	X	X	(JLUX) grass was mowed and norm stickers were placed on tanks.	
6/8/2015	X	X	X	X	(JLUX) the wellheads and piping were painted today. the low and high pressure shutoff valves were painted red and yellow.	
7/20/2015	X	X	X	*	(JLUX) Modern Geosciences conducted an air monitoring inspection today. they found a leak at the separator 2H mallard box. Also the norm level was above 50 at the wellhead 1H.	
8/13/2015	*	*	*	*	(JLUX) NO LEAKS DURING INSPECTION. TEMP COMPRESSOR ON LOCATION UNTIL THE COMPRESSOR AT THE STATION CAN BE REMOVED.	
9/29/2015	X	X	X	X		

10/8/2015	X	X	X	X	(JLUX) replace wind sock	
10/28/2015	*	*	*	*		
11/11/2015	*	*	*	*		
12/15/2015	X	X	X	X		
1/11/2016	X	X	X	X		
1/19/2016	*	*	*	*	(JLUX) Air monitoring inspections conducted by Modern Geosciences. No leaks found on site but need to replace a few norm stickers on tanks.	
1/29/2016	*	*	*	*	(JLUX) Re-inspection done. NORM stickers placed on wellheads and tanks.	
2/12/2016	*	*	*	*		
3/15/2016	X	X	X	X	(JLUX) Well #2H is shut in at this time	
4/5/2016	X	X	X	X		
5/9/2016	*	*	*	*	(JLUX) tall weeds and grass	
6/6/2016	X	X	X	X	(JLUX) the grass was mowed around the wellheads and containment area.	
7/11/2016	*	*	*	*	(JLUX) grass around pad and wellheads needs to be mowed.	
7/20/2016	*	*	*	*	(JLUX) air monitoring inspections with modern geosciences. leaks found on site. notified operator. grass was mowed.	
8/8/2016	*	*	*	*	(JLUX) reinspection done.	
8/24/2016	*	*	*	*		
9/8/2016	*	*	*	*		
10/11/2016	*	*	*	*	(JLUX) tall weeds near the wellheads. A leak was found at mallard box on separator 1H. operator was notified.	

10/26/2016	*	*	*	*	(JLUX) the leak was fixed and tall weeds and grass mowed	
11/11/2016	*	*	*	*		
12/20/2016	*	*	*	*		
1/9/2017	*	*	*	*		
1/30/2017	*	*	*	*	(JLUX) air monitoring inspection conducted by modern goesciences today. leaks at separators and piping. operator notified of issues.	
2/15/2017	*	*	*	*	(JLUX) operator is fixing the pipe at the separator today. reinspection tomorrow	
2/16/2017	*	*	*	*	(JLUX) conducted reinspection. the pipe was replaced at the separator. no leaks found.	
3/21/2017	*	*	*	*		
4/6/2017	*	*	*	*		
4/21/2017	*	*	*	*	(JLUX) conducted emergency response meeting with operator.	
5/9/2017	*	*	*	*		
5/30/2017	*	*	*	*		
6/16/2017	*	*	*	*	(JLUX) tall weeds and grass	
7/7/2017	*	*	*	*	(JLUX) grass was mowed.	
7/21/2017	*	*	*	*	(JLUX) Air monitoring inspections were conducted by Modern Geosciences. Leak was found at separator. Notified operator.	
8/7/2017	*	*	*	*		
8/23/2017	*	*	*	*	(JLUX) re-inspections done. no leaks	
9/21/2017	*	*	*	*		
10/3/2017	*	*	*	*		
10/24/2017	*	*	*	*		

11/13/2017	*	*	*	*	(JLUX) Conducted monthly inspection. No violations found on site.	
12/27/2017	*	*	*	*	(JLUX) no leaks found onsite.	
1/10/2018	*	*	*	*	(JLUX) no issues.	
1/17/2018	*	*	*	*	(JLUX) Air monitoring inspections were conducted by Modern Geosciences today. No leaks were found during the inspection.	
2/7/2018	*	*	*	*	(JLUX) reinspection. no leaks found.	
3/22/2018	*	*	*	*	(JLUX) no issues.	
4/5/2018	*	*	*	*	(JLUX) no leaks found during inspection.	
5/8/2018	*	*	*	*	(JLUX) no issues on site.	
6/5/2018	*	*	*	*	(JLUX) no issues on site.	
7/18/2018	*	*	*	*	(JLUX) no issues on site.	
7/25/2018	*	*	*	*	(JLUX) air monitoring inspection conducted by modern geosciences today. no leaks found during inspection. tall weeds and grass around wellheads.	
8/22/2018	*	*	*	*	(JLUX) no issues.	
9/24/2018	*	*	*	*	(JLUX) no issues.	
10/26/2018	*	*	*	*	(JLUX) no issues.	
11/16/2018	*	*	*	*	(JLUX) no issues.	
12/4/2018	*	*	*	*	(JLUX) no issues	

1/8/2019	*	*	*	*	(JLUX) no issues	
1/14/2019	*	*	*	*	(JLUX) air monitoring inspection was conducted with modern geosciences. no leaks were found on site. wells were shut in.	
2/21/2019	*	*	*	*	(JLUX) wells are shut in. no leaks found. well are getting plugged and abandoned in April.	
3/11/2019	*	*	*	*	(JLUX) no issues	
4/15/2019	*	*	*	*	(JLUX) no issues.	
5/3/2019	*	*	*	*	(JLUX) They moved the rig on tuesday and set up. the crew started work on Thursday. The crew work today. They cut casing and set two plugs. They will finish the other two plugs on Monday. RRC inspector (Jared) came to the gas well pad to witness the setting of the second plug.	
5/7/2019	*	*	*	*	(JLUX) STRC crew finished plugging well 5h on Monday and moved over to the other well. They have been trying to kill the well all day and havent been successful. They hope to kill the well before 7pm tonight.	
5/9/2019	*	*	*	*	(JLUX) STRC cut casing today and will be removing casing from hole. They should finish removing casing tomorrow.	
5/10/2019	*	*	*	*	(JLUX) Pouring cement today and setting plugs. STRC crew will be done today plugging well and move to FR I pad on Monday.	
6/6/2019	*	*	*	*	(JLUX) wells are plugged and pipe risers are installed. ER is in the process of reclaiming pad site. Crews should be working on pad this month.	
7/12/2019	*	*	*	*	(JLUX) no work is being done as of yet. operator is preparing to reclaim pad site.	

8/7/2019	*	*	*	*	(JLUX) not working on the pad just yet.	
8/16/2019	*	*	*	*	(JLUX) crew on site cleaning out tanks and breaking down the containment area and piping.	
9/5/2019	X	X	X	X	crews have been working on removing tanks and equipment from site. pipe markers were removed. operator was notified of the issue. They will be removing the base/gravel soon.	
9/23/2019	*	*	*	*	a crew was on site with truck and trailer removing the pipeline pipe. all the equipment is gone. they still need to remove dirt from pad.	
10/2/2019	*	*	*	*	pad is being reclaimed.	
10/16/2019	*	*	*	*	pad is getting reclaimed. the site is almost done. the base needs to be removed and seeded.	
11/18/2019	*	*	*	*	checked on pad site. the operator has cleared the pad. still in the process of reclaiming pad.	
12/3/2019	*	*	*	*	operator has cleared the pad and gravel. waiting on operator to notify me that pad site is completely reclaimed.	
1/14/2020	*	*	*	*	The operator had completely reclaimed pad site and installed pipe risers.	
2/7/2020	*	*	*	*	Post Production inspection conducted today with Modern Geosciences.	